



567-101 Metri-Pack Pin Removal Tool


PROCEDURE:

- 1. Use a small screwdriver or other prying tool to gently remove the protective cover from the back of the connector. **NOTE:** Be careful not to over extend the tabs on the cover or it will not securely fasten during re-installation.
- 2. Gently insert # 567-101 removal tool into the small slot above the pin on front of the connector. It should not require much force and you should feel the tool bottom out solidly in the connector after roughly 1/4".
- 3. With the removal tool still inserted fully in the cavity, gently pull on the wire to remove it.
- 4. If you will not be putting a sealed wire back in the cavity then you should now install one of the cavity plugs supplied with tool 567-101.
- 5. Re-install protective cover on back of connector.









199R11486 Date: 1-11-18