

Camshaft Specifications

Engine Type Part Number 24502586 SBC

"Hot" Cam

1500-5500 rpm 1986 present Gen1 and Gen 2 engines

**Engine Family** 

ENG. RPM Range Lifter Type Hyd Roller

Intake	ke	Exhaust	
Lobe Lift: 0.328	28	.328"	No.
Gross Valve Lift: .525"	5"	.525"	Note; Measured @ valve with 1.6 rocker
Lobe Centerline: 109 degree	gree	115 degree	
<del>.</del> T	2	281	Note; Duration measured @ cam lift
Duration @ .050": 219	9	228	Note; Duration measured @ cam lift
Rocker Arm Ratio: 1.6	6	1.6	
Valve Adjustment: zero lash	lash	zero lash	
Lobe Seperation	98 98 9	112	AG
Valve lift with 1.5 rocker ratio is .492"	.492"		A 51
Spring Recommendation		Part Number:	12551483
Outside Diameter: 1.337"	37"	Note; It is installers	Note; It is installers responsibility to check for proper valve guide
Installed Height: 1.780"	80"	to spring retai	to spring retainer clearance. Recommended minimum
Seat Load: 101 lbs	lbs	clearance is 1	clearance is .100". Also inspect spring installation for coil bind.
Solid Height: 1.215"	5"	Improper sprin	Improper spring installation can lead to camshaft damage.

enan sansk block em jess proc Denasen poljednig bys Gent Dock Lamas Tols camshall w